

On November 28, 2016, the IEQ team at Stevens Forest Elementary conducted the first semester Indoor Environmental Quality (IEQ) walk-through. During the walk-through, a small patch of mold was discovered on a piece of wood behind a loose piece of back-splash laminate behind the sink in the staff lounge. The discovery was immediately reported to the appropriate HCPSS department for investigation.

On November 29, 2016 HCPSS facilities removed the wood strip and laminate covering that contained mold. The sink faucet was inspected and no leaks were found. A new wood strip and laminate covering were installed and sealed to prevent future water damage.